



U.S. Department
of Transportation
**Federal Aviation
Administration**

Aircraft Certification Service
Compliance & Airworthiness Division

Atlanta ACO Branch
1701 Columbia Ave.
College Park, Georgia 30337

October 3, 2019

In Reply, Reference FAA Correspondence #: 7A0-19-11313

Prashant Chillamcharla
Delta Flight Products, Inc
3980 Tradeport Blvd, Building 1200
Atlanta, GA 30354

Subject: Flammability Test Facility located in Atlanta, GA.

Dear Mr. Chillamcharla:

At your request, the Atlanta ACO completed our review of your flammability test facility in Atlanta, GA on November 19, 2018. The Atlanta ACO has also reviewed the Delta Flight Products Flammability Validation Results listed in document 15D99R914 Rev. I/R dated 8/23/2019 and we concur with the results in this report. As of this date, we find your facility and procedures are acceptable to conduct flammability testing when conducted in accordance with the following Flammability Test Equipment and Procedures to generate data for compliance to 14 CFR Part 25, Appendix F.


- DFPPS-040 Rev - 45 Degree Bunsen Burner Test Procedure
- DFPPS-041 Rev - 60 Degree Bunsen Burner Test Procedure
- DFPPS-042 Rev - Horizontal Bunsen Burner Test Procedure
- DFPPS-043 Rev - Smoke Density Chamber Test Procedure
- DFPPS-044 Rev - Heat Release Chamber Test Procedure
- DFPPS-045 Rev - Vertical Bunsen Burner Test Procedure.

It should be recognized that although we find your facility and procedures acceptable, when generating certification data, an FAA approved test plan, conformed test specimens and test setup, and FAA test witnessing is still required.

This acceptance applies only to the subject facility and procedures evaluated. Relocation or modification of the test apparatus or revisions to the accepted procedures may require additional inspections. Changes to these items or any other change that may affect this acceptance should be communicated to the Atlanta ACO for further evaluation. In addition, your facility and procedures will be subject to periodic reviews to ensure your continued quality of testing.

If you have further questions, feel free to contact Mr. Tony White by email at tony.white@faa.gov or by phone at 404-474-5542.

Sincerely,

A handwritten signature in black ink, appearing to read "Corey Spiegel". The signature is fluid and cursive, with a prominent initial "C" and a long horizontal stroke at the end.

Corey Spiegel
Manager, Airframe Section
Atlanta ACO Branch